



POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT



POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT



POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT





POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT





POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE TREATMENT



POLYCHROME ITALIAN CORNER CUPBOARD:
AFTER TREATMENT



POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT





POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT
(SILK "BANDAIDS" WERE USED EXTENSIVELY TO STRENGTHEN.)





POLYCHROME ITALIAN CORNER CUPBOARD: PROCESS
(SILK "BANDAIDS" WERE USED EXTENSIVELY TO STRENGTHEN.)





POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT





POLYCHROME ITALIAN CORNER CUPBOARD: PROCESS
(SHIMS WERE USED AS THE PREVIOUS INAPPROPRIATE REPAIR SET THE LEG
AT AN ANGLE DUE TO LOSSES, WHICH WAS CORRECTED BY SHIMS.)





POLYCHROME ITALIAN CORNER CUPBOARD: PROCESS





POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT
(NOTE THE C-CLAMP MARK FROM A SLOPPY PREVIOUS REPAIR.)





POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT

(THE FLOOR OF THE TABLE WAS DISINTEGRATING; WE SAVED THE TOP
BOARDS AND SUPPORTED THEM FROM UNDERNEATH..)





POLYCHROME ITALIAN CORNER CUPBOARD: PROCESS





POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT
(SILK "BANDAIDS" WERE USED EXTENSIVELY TO STRENGTHEN.)





POLYCHROME ITALIAN CORNER CUPBOARD:
BEFORE AND AFTER TREATMENT
(SILK "BANDAIDS" WERE USED EXTENSIVELY TO STRENGTHEN;
PARTS OF THE ROOF OF THE CUPBOARD WERE REPLACED.)

