



358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, BEFORE TREATMENT



358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, AFTER TREATMENT



358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, AFTER TREATMENT



358 OLD WOOD POLYCHROME AFRAME

MASON MONTEREY CHAIR, AFTER TREATMENT

Note the twist to the back due to the misaligned seat + skewed splat mortice.



358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, AFTER TREATMENT



358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, AFTER TREATMENT



358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, AFTER TREATMENT



358 OLD WOOD POLYCHROME AFRAAME
MASON MONTEREY CHAIR, AFTER TREATMENT





358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, BEFORE & AFTER TREATMENT





358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, BEFORE AND AFTER TREATMENT





358 OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIR, AFTER TREATMENT



ALL OLD WOOD POLYCHROME AFRAME
MASON MONTEREY CHAIRS, AFTER TREATMENT

